

www.nandira.com



Go-spot anti-spatter

Spatter-Free Welding

Enhanced Weld Quality


Reduced Cleanup Effort

Improved Work Efficiency


Cost Savings



WATER BASED SOLUTION







Just apply / spray on the surface before welding









How to use?

- Shake the bottle thoroughly before use.
- Apply a thin, even coat on the welding area by spraying or brushing.
- Once spraying is done, proceed with welding.

Our Anti-spatter formulation forms an invisible barrier on the weld surface that effectively deflects molten weld droplets, preventing them from adhering to the surrounding area.



Other Products:-









Scan to know more